



LAWRENCE  
LIVERMORE  
NATIONAL  
LABORATORY

# Mastering Layers

G. Beer

April 6, 2007

PTC User World Event 2007  
Tampa, FL, United States  
June 3, 2007 through June 6, 2007

## **Disclaimer**

---

This document was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor the University of California nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or the University of California. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or the University of California, and shall not be used for advertising or product endorsement purposes.



**WORLD  
EVENT™  
2007**

# Mastering Layers

*Glenn Beer*

*Photon Science & Applications*

*Lawrence Livermore National Laboratory*

**UCRL-CONF-229779**

***This work was performed under the auspices of the U.S. Department of Energy by the University of California, Lawrence Livermore National Laboratory, under Contract No. W-7405-Eng-48.***

[illegible]

# I Intend to show...

---

- How to easily predict the visibility of items, depending on the layer status. (Isolate, Hidden, Unhidden)
- How to make effective use of putting items onto multiple layers.
- And, I'll demonstrate some *cool mapkeys*, that are based the info presented. They allow the *quick* and *easy* clean up of the layers of an entire assembly and it's components.




# So What Does Mastering Layers Involve?

---

- Understanding exactly what has been put onto the layers.
- Knowing *"Invisibility Rule #1"*.
- Knowing how layer status impacts visibility.
- The effective use of placing items onto multiple layers.
  - This makes it easier to **choose what you want to see**, instead of everything you don't.

# All Features Have Entities...

- Datum Features - Axis, Csys, Curves, Planes, Quilts, Tag Names...



# Invisibility Rule #1

---

- *Once an item is rendered invisible; every sub item, in that branch of the model, is rendered invisible.*




\* This is a fundamental in Pro/Engineer.




# Layer Status Diagram (Parts)

---




# Layer Status Diagram (Parts)

---




# Layer Status Diagram (Parts)






# Layer Status Diagram (Parts)




# Layer Status Diagram (Parts)




Remember, Invisibility Rule #1 still applies.



# Choosing What You Want to See (Isolate)



# Layer Status Diagram (Assemblies)



Remember, Visibility Rule #1 still applies.

- *Every aspect of layers in an assembly is the same as in parts, until a component is added to a layer – then things change, boy do they!*

# Layer Status (Assemblies)

---

*About putting components on layers...*

*My Advice: Don't do it!*

*Simplified Reps are better for managing  
component visibilities*



# Putting It Together

---

- Use Isolate in place of Unhidden.
  - Putting items on multiple layers becomes useful.
  - Creating new layers need not disturb existing layers.
  - Choose what you want to see, instead of everything you don't.
- Create, all inclusive, default layers only for the items found in the majority of your models. Don't remove items from them, with Isolate, it isn't necessary.
- Create layers that suit your needs.
- Save all layers with the status Hidden. Make exceptions only for things that need to be seen in **ALL** upper assemblies.

# Demo: Config.pro, Drawing.dtl & Mapkeys

---

- Config.pro

- no def\_layer options
- add\_lower\_level\_comps\_to\_layer no
- Make the environment display options on by default.

- Drawing.dtl

- ignore\_model\_layer\_status      yes
- draw\_layer\_overrides\_model      yes



# Demo's

---

- Cleaning an Assembly

- Using find to create layers.
- Using the extend function to create layers, with rules, **recursively**.
- Searching for items in the layer tree.
- Using the selector to manipulate the layer tree.
- How to distinguish between entities and features.
- The quick cleanup demo.

- Drawings & Parts

- Create drawing layers, use them to keep changes to the model from impacting the drawing.

- Skeletons

- Layers to fit special requirements.



**WORLD  
EVENT™  
2007**

